

## **State Water Resources Control Board**



## **Division of Water Quality**

1001 I Street, Sacramento, California 95814 ♦ (916) 341-5870 Mailing Address: P.O. Box 100, Sacramento, California 95812-0100 FAX (916) 341-5463 ♦ Internet Address: http://www.waterboards.ca.gov

## ~ Sent Via Email~

December 5, 2006

To: Interested Parties

## RESULTS OF SECONDARY CONTAINMENT PERFORMANCE SURVEY

On February 23, 2003, the State Water Resources Control Board (State Water Board) Underground Storage Tank (UST) Program staff sent out a survey to inquire about the frequency of secondary containment failures, the reasons for secondary containment failures, and to acquire information on the pass/fail criteria of the different methods used for testing. Attached please find the Results of the Secondary Containment Performance Survey.

If you have questions regarding this document, contact the UST Program at (916) 341-5775 or via e-mail at <a href="mailto:ust@waterboards.ca.gov">ust@waterboards.ca.gov</a>.

Sincerely,

Original signed by

Laura Chaddock, Chief Underground Storage Tank Program Leak Prevention Technical Unit